

**SETSCO SERVICES PTE LTD**

18 Teban Gardens Crescent
Singapore 608925
Tel : (65) 6566 7777
Fax: (65) 6566 7718
Website: www.setsco.com
Business Reg. No. 196900269D

Our Ref : CH-11244/LZP/1**Date : 05/09/2006****TEST REPORT**

Page 1 of 1

(This Report is issued subject to the terms & conditions set out below)

Subject : Analysis on sample submitted by Multi-Sindo (Singapore) Pte Ltd on 24/08/2006 and testing commences on 24/08/2006.

Tested For : **Multi-Sindo (Singapore) Pte Ltd**
1 Goldhill Plaza #02-19
Singapore 308899
Attn : Mr Guy de Souza / Mr Christopher Pua

Test Methods : 1) EPA 3052 : Microwave acid digestion for Cd, Pb & Hg
2) EPA 6010B : ICP-OES analysis for Cd, Pb & Hg
3) EPA 3060A : Alkaline digestion for Hexavalent Chromium (Cr⁶⁺)
4) EPA 7196A : Colorimetric by UV-VIS Spectrophotometry for Hexavalent Chromium (Cr⁶⁺)

Sample Description : INSULTEC
Lot No. : 25E06

Results :

| Item No. | Element | MDL (ppm) | Result (ppm) |
|----------|---|-----------|--------------|
| 1 | Cadmium (Cd) | 1 | Not Detected |
| 2 | Lead (Pb) | 10 | 33.2 |
| 3 | Hexavalent Chromium (Cr ⁶⁺) | 2 | Not Detected |
| 4 | Mercury (Hg) | 1 | Not Detected |


LEI ZHI PEI
MANAGER
BIOLOGICAL & CHEMICAL TECHNOLOGY DIVISION

Terms & conditions:

- (1) The Report is prepared for the sole use of the Client and is prepared based upon the Item submitted, the services required by the Client and the conditions under which the Services are performed by SETSCO. The Report is not intended to be representative of similar or equivalent Services on similar or equivalent Items. The Report does not constitute an endorsement by SETSCO of the item.
- (2) SETSCO agrees to use reasonable diligence in the performance of the Services but no warranties are given and none may be implied directly or indirectly relating to the Services, the Report or the facilities of SETSCO.
- (3) The Report may not be used in any publicity material without the written consent of SETSCO.
- (4) The Report may not be reproduced in part or in full unless approval in writing has been given by SETSCO.
- (5) SETSCO shall under no circumstances be liable to the Client or its agents, servants or representatives, in contract, tort (including negligence or breach of statutory duty) or otherwise for any direct or indirect loss or damage suffered by the Client, its agents, servants or representative howsoever arising or whether connected with the Services provided by SETSCO herein.

**SETSCO SERVICES PTE LTD**

18 Teban Gardens Crescent
Singapore 608925
Tel : (65) 6566 7777
Fax: (65) 6566 7718
Website: www.setsco.com
Business Reg. No. 196900269D

Our Ref : CH-11244/LZP/2**Date : 05/09/2006****TEST REPORT**

Page 1 of 5

(This Report is issued subject to the terms & conditions set out below)

Subject : Analysis on sample submitted by Multi-Sindo (Singapore) Pte Ltd on 24/08/2006 and testing commences on 24/08/2006.

Tested For : **Multi-Sindo (Singapore) Pte Ltd**
1 Goldhill Plaza #02-19
Singapore 308899
Attn : Mr Guy de Souza / Mr Christopher Pua

Test Method : VOC by Headspace GC-MSD
Weight of sample analyse : 1.09070 g
Standard used : 5 µL 1% v/v Decane
Response area : 17,325,227
Sampling temperature : 85°C
Purge time : 16 hrs

Sample Description : INSULTEC
Lot No. : 25E06

Results :

| Compound | Result (g/L) | Method Detection Limit (g/L) |
|-----------------------------------|--------------|------------------------------|
| Volatile Organic Compounds | 0.038 | 50.00 |
| Total Halogenated Organic Solvent | Not Detected | - |
| Total Aromatic Organic Solvent | 0.004 | - |
| Epichlorohydrin | Not Detected | - |

Note : GC-MS chromatogram and Library Search Reports are attached on the following pages.

LEI ZHI PEI
MANAGER
BIOLOGICAL & CHEMICAL TECHNOLOGY DIVISION

Terms & conditions:

- (1) The Report is prepared for the sole use of the Client and is prepared based upon the Item submitted, the services required by the Client and the conditions under which the Services are performed by SETSCO. The Report is not intended to be representative of similar or equivalent Services on similar or equivalent Items. The Report does not constitute an endorsement by SETSCO of the Item.
- (2) SETSCO agrees to use reasonable diligence in the performance of the Services but no warranties are given and none may be implied directly or indirectly relating to the Services, the Report or the facilities of SETSCO.
- (3) The Report may not be used in any publicity material without the written consent of SETSCO.
- (4) The Report may not be reproduced in part or in full unless approval in writing has been given by SETSCO.
- (5) SETSCO shall under no circumstances be liable to the Client or its agents, servants or representatives, in contract, tort (including negligence or breach of statutory duty) or otherwise for any direct or indirect loss or damage suffered by the Client, its agents, servants or representative howsoever arising or whether connected with the Services provided by SETSCO herein.



SETSCO SERVICES PTE LTD

18 Teban Gardens Crescent
Singapore 608925
Tel : (65) 6566 7777
Fax: (65) 6566 7718
Website: www.setsco.com
Business Reg. No. 196900269D

Our Ref : CH-11244/LZP/3

Date : 05/09/2006

TEST REPORT

Page 1 of 1

(This Report is issued subject to the terms & conditions set out below)

Subject : Analysis on sample submitted by Multi-Sindo (Singapore) Pte Ltd on 24/08/2006 and testing commences on 24/08/2006.

Tested For : **Multi-Sindo (Singapore) Pte Ltd**
1 Goldhill Plaza #02-19
Singapore 308899
Attn : Mr Guy de Souza / Mr Christopher Pua

Test Method : ASTM D3828-98

Sample Description : INSULTEC
Lot No. : 25E06

Results :

| Determination | Result |
|---------------|--------|
| Flashpoint | >61°C |

Note : Test was performed in conjunction with Intertek Testing Services (S) Pte Ltd.

LEI ZHI PEI
MANAGER
BIOLOGICAL & CHEMICAL TECHNOLOGY DIVISION

Terms & conditions:

- (1) The Report is prepared for the sole use of the Client and is prepared based upon the Item submitted, the services required by the Client and the conditions under which the Services are performed by SETSCO. The Report is not intended to be representative of similar or equivalent Services on similar or equivalent Items. The Report does not constitute an endorsement by SETSCO of the Item.
- (2) SETSCO agrees to use reasonable diligence in the performance of the Services but no warranties are given and none may be implied directly or indirectly relating to the Services, the Report or the facilities of SETSCO.
- (3) The Report may not be used in any publicity material without the written consent of SETSCO.
- (4) The Report may not be reproduced in part or in full unless approval in writing has been given by SETSCO.
- (5) SETSCO shall under no circumstances be liable to the Client or its agents, servants or representatives, in contract, tort (including negligence or breach of statutory duty) or otherwise for any direct or indirect loss or damage suffered by the Client, its agents, servants or representative howsoever arising or whether connected with the Services provided by SETSCO herein.

**SETSCO SERVICES PTE LTD**

18 Teban Gardens Crescent
Singapore 608925
Tel : (65) 6566 7777
Fax: (65) 6566 7718
Website: www.setsco.com
Business Reg. No. 196900269D

Our Ref : CH-11244/LZP/4**Date : 07/09/2006****TEST REPORT**

Page 1 of 1

(This Report is issued subject to the terms & conditions set out below)

Subject : Analysis on sample submitted by Multi-Sindo (Singapore) Pte Ltd on 24/08/2006 and testing commences on 24/08/2006.

Tested For : **Multi-Sindo (Singapore) Pte Ltd**
1 Goldhill Plaza #02-19
Singapore 308899
Attn : Mr Guy de Souza / Mr Christopher Pua

Test Method : Solvent Extraction GCMS

Sample Description : INSULTEC
Lot No. : 25E06

Results :

| Determination | Unit | Result | Detection Limit |
|---------------|-------|--------------|-----------------|
| Formaldehyde | µg/Kg | Not Detected | 30 |

Note : Test was performed in conjunction with Marchwood Scientific Services Ltd.

LEI ZHI PEI
MANAGER
BIOLOGICAL & CHEMICAL TECHNOLOGY DIVISION

Terms & conditions:

- (1) The Report is prepared for the sole use of the Client and is prepared based upon the Item submitted, the services required by the Client and the conditions under which the Services are performed by SETSCO. The Report is not intended to be representative of similar or equivalent Services on similar or equivalent Items. The Report does not constitute an endorsement by SETSCO of the Item.
- (2) SETSCO agrees to use reasonable diligence in the performance of the Services but no warranties are given and none may be implied directly or indirectly relating to the Services, the Report or the facilities of SETSCO.
- (3) The Report may not be used in any publicity material without the written consent of SETSCO.
- (4) The Report may not be reproduced in part or in full unless approval in writing has been given by SETSCO.
- (5) SETSCO shall under no circumstances be liable to the Client or its agents, servants or representatives, in contract, tort (including negligence or breach of statutory duty) or otherwise for any direct or indirect loss or damage suffered by the Client, its agents, servants or representative howsoever arising or whether connected with the Services provided by SETSCO herein.