

INSULTEC AUSTRALIA PTY LIMITED

ABN 93 092 861 008



Manufacturing Site: U1/481 Victoria Street, Wetherill Park, NSW 2164 Australia
Registered Office Address: 10 Pacific Highway, Calga, NSW 2250 Australia

Tel: +61 (0)2 4375 1023 Fax: (02) 4375 1053
Email: insultecaustralia@bigpond.com
Website: www.insultecaustralia.com.au

PRODUCT DATA SHEET INSULTEC GLAZE COAT

- Water clear acrylic, excellent resistance to UV
- Very good durability
- High resistance to finger marks, minerals, alkalis, grease etc.
- Very good self-cleaning properties.

RECOMMENDED USES

As a clear protective coating over masonry surfaces.
As a sealer coat over Matt acrylics.
As a sealer coat over Insultec membranes.

APPLICATION DATA

Apply only over clean, dry surfaces, which have been thoroughly cleaned or water blasted For bare new or old masonry apply two coats by brush or airless spray, allowing four hours drying time between two coats. Over previously painted surfaces apply one or two coats by airless spray. Ensure that previously painted surfaces have been allowed to cure for at least 48 hours or a patchy finish may occur. Clean up with water when wet or solvents when dry.

COVERAGE

Approximately 4 - 6 sq.metres per litre

PRECAUTIONS

Provide adequate ventilation during application. When spray painting, applicators should comply with provisions of the relevant spray-painting regulations. Avoid contact with skin and eyes. Wear protective goggles and gloves when handling the material. In case of skin contact, remove contaminated clothing and clean skin with white spirit then wash skin thoroughly with soap and water. Seek medical attention if eyes are affected by splash.

PACKAGING

20 litre pails.
4 litre cans

DISCLAIMER

The data contained herein is based upon information, which the company believed to be reliable at the time of preparation of this data sheet. No responsibility can be accepted, or any express or implied warranty given where performance of the product is affected by surface preparation, method of application or any other circumstances beyond the control of this company.

July 2012